

# Goat Gun SVD Assembly Guide



Scan for video



## Hardware List

- [1] spring
- [1] bipod lock
- [5] screws
- [1] screwdriver with magnet

## Parts List

- |                    |                                |                      |
|--------------------|--------------------------------|----------------------|
| A. Bolt carrier    | E. Charging handle             | H. Magazine          |
| B. Upper handguard | F. Dust cover                  | I. Non-firing rounds |
| C. Lower handguard | G. Receiver and stock assembly | J. Scope             |
| D. Barrel assembly |                                |                      |



- 1** Put receiver (G) into barrel (D). Insert screw where holes align on top of barrel.



- 4** Slide charging handle (E) into receiver (G). Put spring on bolt carrier (A). Insert into charging handle.



- 6** Screw scope (J) onto left side.



- 2** Place handguards (B & C) around barrel (D). Push together and towards back of gun until they snap into place.



- 6** Place dust cover (F) over bolt carrier (A) and lock into place



- 7** Load non-firing rounds (I) into magazine (H). Slide magazine until it clicks into place, and show off your Goat Gun.



- 3** Slide bipod retainer over handguards. Install bipod lock on right side.