

## ASSEMBLY GUIDE



TIME TO HAVE A LITTLE FUN >>

## AK-12 ASSEMBLY GUIDE



## PARTS LIST

- A. Receiver
- B. Dust Cover
- C. Muzzle
- D. Magazine
- E. Stock

- F. Display Stand
- G. Charging Handle
- H. Dummy Rounds
- Stand Anchor
- J. Dust Cover Pin

## HARDWARE LIST

- (1) Screw for Display Stand
- (1) Screwdriver



Insert charging handle with the flat end toward the barrel.



Slide spring cover bolt carrier. Front of bolt carrier inserts into charging handle. Rear sits in the channel.



Slide on dust cover ensuring rear hooks attach and front holes align.



Insert dust cover pin and rotate clockwise until it latches on handguard.




Depress lever to slide stock over buffer tube.



Slide muzzle break on with longer portion on the bottom of barrel. Rotate approx ½ turn to lock muzzle into place.

Note: Muzzle break will loosen if turned more than approx ½.



Load dummy rounds into mag. Insert mag into mag well until it clicks into place.



Attach stand insert piece to stand using the included screws. Show off your GoatGun!



SCAN FOR IN-DEPTH GUIDE



FI GOATGUNS @ GOAT.GUNS GOATGUNS.COM